# DEVELOPMENT MANAGEMENT SITE MONITORING REPORT 2017



# PRESTON NEW ROAD SHALE GAS EXPLORATION SITE

MONITORING VISIT - 26th January 2017

SITE REFERENCE NO. - 5/M.2/93

Development Management Group Environment Directorate Lancashire County Council County Hall PO Box 100 Preston PR1 0LD

Telephone: 01772 531929 Fax: 01772 533898 Email: <u>DevCon@lancashire.gov.uk</u>



Site Name	Preston	New Road	File Ref	5/M.2/93
Inspector's Name	Jonathan Haine		Date	26 <sup>th</sup> January 2017
Site Operator	Cuadrilla Resources		Met with	Nick Mace
Address	Preston New Road, Little Plumpton, Preston.		Photos taken	No
			Weather Conditions	Cold, dry, southerly wind
Monitoring Visit	Fee	N/A		
			Time	09.30 -11.30

## Site History

Planning permission for the development of an exploration wellsite for shale gas was granted by the Secretary of State for Communities and Local Government on 6<sup>th</sup> October 2016.

The planning permission is subject to 49 conditions, a number of which require details of various matters to be submitted to and approved in writing by the County Planning Authority prior to the commencement of development. These schemes were approved by the County Council on 4thJanuary 2017.

Development works on the site commenced on 5<sup>th</sup> January 2017.

During the monitoring visit, the work being undertaken was restricted to the construction of the access off the A583.

Compliance with Planning permission LCC/2014/0096 dated 6<sup>th</sup> October 2017 – Current Situation

Requirement No	Subject matter	Comments	
1	Time limits for commencement	Commencement within 3 years of the date of the permission – development has already commenced.	
2	Time limits for completion of the development	Development has to be completed and site restored within 75 months of commencement date (condition 3)	
3	Notice of Commencement of development	In compliance – written notice of the commencement of the development was supplied to the County Council on 4 <sup>th</sup> January 2017. Further notifications will be needed at later stages of the project.	

4 5	Development carried out         in accordance with         approved drawings and         documents         Copy of decision notice         and approved plans made         available in site office	Development appears to be in general accordance with approved documents – see other conditions for detail. Since the previous monitoring visit, works had continued to construct the access including laying of kerbs and sub base to the access. A temporary compound had also been established for welfare and office facilities. These works appeared to be in accordance with the approved drawings. Site office now established. Electronic version of planning permission was available and site contractor (AE Yates) had hard copies of
6	Details for removal of	access plans which were being referred to – in compliance.
6	plant upon cessation of each phase	Condition only applies upon completion of drilling activities and subsequent phases. No requirement under condition 6 in terms of site construction phase
7	Condition not used	
8	Scheme for construction of site access	Scheme approved on 4/1/17. Since previous visit, access has been widened to its full width and radii kerbs installed. Stone was being imported to form sub base to access road and bell mouth prior to surfacing on 27/01/17. Hedgerow on either side of access still requires lowering to create approved visibility splay. It was discussed that the central island will be approximately 8 metres further east than shown on the s278 plan – this change has been agreed with LCC Highways. It is also proposed not to construct the cattle grid at the junction of the access road and bell mouth in order to reduce noise and remove possible security implications. Topsoil had been spread over areas outside of the radii kerbs to restore and landscape the disturbed area.
9	Condition not used	-
10	Wheel cleaning measures	Scheme approved on 4/1/17. Wheel cleaning measures were not in place at time of visit. The condition requires them to be installed throughout the construction phase. HGV's delivering stone were reversing onto previously tipped areas of sub base. However, this material is relatively clean and there was no evidence of any tracking out of material onto Preston New Road. A road sweeper is in attendance at the end of each working day.

11	Submission of troffic	Troffic management plan approved on A/A/AZ
11	Submission of traffic management plan	Traffic management plan approved on 4/1/17. Cuadrilla are supplying details of lorry routing to the County Council. Since the last visit, all HGV's appear to have complied with the approved vehicle routing. The vehicles that were queued on the A583 waiting to access the site had all approached from Junction 4.
12	Construction method statement	Scheme approved on 4/1/17. A temporary compound area for the siting of cabins had been established using the metal sheeting. It is understood that the cabins would shortly be relocated to a new temporary compound nearer to the access point to allow space to create the exploration compound. Temporary security (heras) fencing had been erected around the entire site boundary.
		A number of skips had been brought onto the site to allow for segregation of waste materials.
13	Scheme of monitoring of baseline highway conditions	Scheme submitted and approved on4/1/17. It is understood that the first baseline survey was undertaken on 23/12/16. The video recording has been made available to LCC Highways as a record of road conditions at the commencement of the project.
14	Condition not used	
15	Stripping of soils	Some stripping of topsoil had taken place within the proposed exploration compound area. It is understood that these works had been undertaken for site investigation purposes. The stripped soils had been stored in temporary mounds and will be moved to the perimeter screening mounds as part of the main soil stripping contract.
16	No soils exported from site	In compliance – no soils exported.
17	Landscaping of soil mounds	No soil mounds created in their final positions at time of visit
18	All soil mounds to be retained in weed free condition	No soil mounds created in their final postions at time of visit
19	Hours of operation	Limitation to 07.30 – 18.30 M – F and 08.30 – 12.00 Saturdays for construction activities. No complaints about working outside of these hours.
20	Condition not used	
21	Condition not used	
22	Disposal / storage of surface water run off	Condition not relevant until site compound has been constructed

<b>1</b> 2	Containment and dispacel	Temperary tailet facility was an aite for you by
23	Containment and disposal	Temporary toilet facility was on site for use by
24	of foul drainage Buffer zones between	construction personnel.
24		Site compound not yet constructed. Condition
	edge of drilling compound	not applicable at present
25	and perimeter ditches	
25	Condition not used	Cohema annual on 1/1/17. Onerations on
26	Noise management plan	Scheme approved on 4/1/17. Operations on site during visit were not giving rise to
		substantial levels of noise. Any plant being
		used appeared to be fitted with manufacture's
		attenuation measures.
27	Condition not used	
28	Noise monitoring	Two permanent noise monitoring points are in
20	methodology	position at the site. One is close to A583 and
	methodology	another is in the field further from the road.
		The monitoring points have been activated
		and are monitoring for the noise levels stated
		in condition 28. Monitoring point 1 also
		provides for audio recording. The monitoring
		stations automatically download the noise
		information and the County Council is able to
		view the monitoring information on line in the
		event that complaints are received.
29	Noise levels (general	Site activity is at a low level and would not be
	noise levels)	likely to generate levels of noise that would
	,	breach the noise limitations in the condition.
30	Noise levels ( tones and	No noise detected during site visit that would
	impulsive noise)	have any tonal or impulsive characteristics.
31	Maintenance of plant,	In compliance – all plant being used appeared
	equipment and machinery	to be well maintained and was not generating
		undue levels of noise or exhaust emissions.
32	Condition not used	
32A	Dust management plan	Dust management plan approved on 4/1/17.
		Dust monitoring equipment has been installed
		at the site and is being used to record levels
		of dust. Equipment includes frisbe type gauge,
		a directional dust monitor and a monitor to
		record particulates. No dust impacts visible
		during monitoring visit.
33	Lighting	Lighting scheme for construction phase
		approved on 4/1/17. Lighting being used for
		construction activities appears to comply with
		approved scheme. Further details will be
		required for the lighting to be used for the next
		phase of the development (drilling) before this
24	Details for colours of	commences.
34	Details for colours of	Details approved on 4/1/17. None of the plant
	plant, equipment and	covered by this condition has yet been built.
	acoustic fencing	Compliance with condition to be monitored at
34A	Drobibition on display of	future visits.
34A	Prohibition on display of	In compliance
	any corporate logos	

35	Restriction on height of	In compliance – no rig is currently on the site
36	drilling rig Design and location of security fencing	Scheme provides for erection of 2.0 metre high heras fence around site boundary. The fencing that has been erected complies with this specification. No other security fencing had been erected at the time of the site visit.
37	Biodiversity Mitigation Strategy	Strategy was approved on 4/1/17. Hedgerow removal to create access has been undertaken outside of bird nesting season. The remaining lengths of hedgerow to be removed should be undertaken before the end of February. It is understood that the Ecological Clerk of Works has been present during construction works and has undertaken various surveys as proposed in the Mitigation Strategy. These have been supplied to the County Council.
38	Condition not used	
39	Prohibition on trees and hedgerows being removed during bird breeding season	Trees and hedgerows required to construct access were removed in the first week of the development therefore outside of the bird breeding season. The remaining vegetation that needs to be removed / lowered should be undertaken before the end of February.
40 and 41	Scheme of landscaping	Scheme approved on 4/1/17. It is noted that the scheme proposes additional tree and hedge planting in various areas around the site. It is understood that Cuadrilla propose to undertake the landscaping works in the current planting season.
42	Condition not used	
43	Archaeology	Archaeology scheme approved on 4/1/17.
		Some soil stripping has already taken place as discussed under condition 15. It is understood that an archaeologist had been present on site during these operations and there was evidence on site of areas of potential interest being highlighted on the stripped surface with spray paint. It is understood that a small number of finds had been discovered which will be reported in accordance with the approved scheme. Soil stripping had been undertaken using a toothless bucket to ensure creation of a finished surface suitable to identify any archaeology.

45 and 46	Restoration (reduction of access to agricultural access)	No restoration at present time
47	Aftercare	No requirement for aftercare at the present time
48	Community Liaison Group	Scheme for CLG was approved on 4/1/17. LCC is currently making arrangements for selection of community representatives.
49	Reporting of breaches of condition	No material breaches of condition with public health implications have taken place

### **Issues and Actions**

At the time of the visit, the development was restricted to the formation of the access point which was nearing completion. The access design appeared to accord with the approved drawings.

The development works being undertaken were not having a major impact on the environment and appeared to be in compliance with the planning conditions. The issues that had previously occurred in relation to HGV's not following the approved vehicle routing appear to have been resolved and there had been no recent occurrences of HGV's accessing the site via junction 3 M55.

Some limited soil stripping had taken place. The soils were in a reasonably dry and friable condition and the required archaeological supervision had been undertaken. The wheel cleaner was not yet in position but there was no evidence of any mud or other debris being tracked out onto Preston New Road. The required ecological supervision had also been undertaken. It is understood that the landscaping works including those measures included in the Biodiversity Mitigation Plan will be undertaken before the end of March providing that weather conditions are suitable.

During the visit, Cuadrilla were undertaking sampling of water and methane from the four perimeter boreholes.

#### Date of Next Visit

Inspector's Signature

To be arranged

J Haine 27th January 2017